

Change for Unit Maintenance TM5-2430-200-24, page B9.

UNIT PREVENTIVE MAINTENANCE CHECKS AND SERVICES—DEUCE

NEW ADDITION

CAUTION

FAILURE TO REMOVE PROTRUDING CABLES WILL CAUSE DAMAGE TO THE BELTS, FRONT IDLERS, MIDROLLERS AND REAR IDLERS.

10	QUARTERLY	<p>Check drive belts for protruding main/zero degree cables. The 72 main/zero degree cables run lengthwise inside the belt.</p> <p>If main/zero degree cable protrudes, cable must be ground flush with belt surface.</p> <p>If more than 8 ft. of cable is exposed or 28 of the 72 cables are broken belt must be replaced.</p>
----	-----------	--

WARNING

EYE PROTECTION AND GLOVES MUST BE WORN WHEN CUTTING CABLES.

Cut or grind the main/zero degree cables flush with belt.